Remedial Action Report – Site 137 North (AOC 137-1A and AOC 137-2A) and Site 143 (AOC 143-1) Soil Garfield Avenue Group PPG, Jersey City, New Jersey

Appendix J

Non-Hazardous Waste Disposal Documentation (Profiles provided separately)



Appendix J Non-Hazardous Waste Disposal Documentation Site 137 North and Site 143, Garfield Avenue Group PPG, Jersey City, New Jersey

This appendix includes bills of lading (BOLs) for solid non-hazardous wastes which were removed during building demolition or excavation of the Site 143 portion of Phase 3A and Site 137 North portion of Phase 3B North as part of the soil remediation activities being conducted for the Garfield Avenue Group Sites. This appendix also includes BOLs for wastes removed during full-scale remedial activities, wastes generated during groundwater treatment system operation, and wastes not directly loaded during excavation activities (i.e., well installation, mitigation activities, and remedial investigation-related activities that occurred concurrently with remediation).

This appendix also includes some wastes removed during the Site 132 excavation activities, which occurred concurrently with the Site 137 North and Site 143 remediation. In addition, the 2017 BOLs are included for the mitigation activities conducted at Site 137 North and along Carteret Avenue.

Phase	Profile Number	Profile Name	Facility	Loads	Tons
3A	1	NH Concrete	CCIA	38	870.07
3A	2	NH Soils	CCIA	224	5,753.05
3A	3	NH Soils from Stockpile	CCIA	80	2,078.47
3A	4 ^a	Demolition Debris	CEP	8	184.27
3B North	5	NH Concrete	CCIA	58	1,250.98
3B North	6	NH Soils	CCIA	353	8,795.79
3B North	7 ^b	NH DGA	CCIA	2	47.77
3B North	8°	NH Demolition Debris	CEP	34	657.84

Total	797	19,638.24
-------	-----	-----------

Notes:

- a. Bills of lading are not included with this appendix. Profile listing was provided by Clean Earth of Philadelphia. These loads were shipped off site concurrently with the building demolition at Site 143. Some of the waste removed during this time frame also included demolition debris from Sites 132 and 137.
- b. Bills of lading contained in this profile are from the mitigation activities conducted in November 2017 at Site 137 North.
- c. Bills of lading are not included with this appendix. Profile listing was provided by Clean Earth of Philadelphia. These loads were shipped off site at end of the Site 132 building demolition and may have included demolition debris from Site 132, in addition to demolition debris from Site 137.
- CCIA Cumberland County Improvement Authority in Deerfield Township, New Jersey
- CEP Clean Earth of Philadelphia in Philadelphia, Pennsylvania
- DGA dense-graded aggregate
- NH non-hazardous