



Legend

- Exceedance with COPR Present
- Exceedance with No COPR Present
- No Exceedance with COPR Present
- Historical Sample - No Exceedance
- Historical Sample - Exceedance
- Areas Requiring Remediation
- Limit of HDPE Liner
- Spectra Pipeline
- Site Boundary
- ✕ Fence Line

PPG INDUSTRIES, INC.
JERSEY CITY, NEW JERSEY

FIGURE 20
SITES 63 AND 65
LIMIT OF CONTAMINATION (RESIDENTIAL
DIRECT CONTACT EXCEEDANCES IN SOIL)

PROJECT: 112C03562	DATE: FEBRUARY 2013
REV:	BY: JEE CHECK: BD / RO

TETRA TECH

